


FC Bare Fiber Adapter

Features	
Low insertion loss	
Good repeatability	
Easy operation	
Application	
Temporarily connect to bare fiber	
Fiber testing in lab	
Production line of optical fiber devices	

Specifications:

Parameter	Type	FC
Ferrule ID (mm)		0.126 ~ 0.127
Ferrule OD (mm)		2.499
Insertion loss (dB)		≤0.02
Repeatability (dB)		≤0.02
Spring pulling force (dB)		200g
Fiber type		Φ125um SM or MM fiber
Plug times		≥10000 times
Operation temperature		-40 ~ 85 °C

Ordering Information

BFA-FC